

### Men's Health

### 2019 Coding & Payment Quick Reference

Payer policies will vary and should be verified prior to treatment for limitations on diagnosis, coding, or site of service requirements. The coding options listed within this guide are commonly used codes and are not intended to be an all-inclusive list. We recommend consulting your relevant manuals for appropriate coding options.

The following codes are thought to be relevant to Men's Health procedures and are referenced throughout this guide.

To determine whether there are relevant C-codes for any Boston Scientific products, please visit our C-code finder at http://www.bostonscientific.com/en-US/reimbursement/ccode-finder.html.

C-Codes are tracking codes established by the Centers for Medicare & Medicaid Services (CMS) to assist Medicare in establishing future APC payment rates. C-Codes only apply to Medicare hospital outpatient claims. They do not trigger additional payment to the facility today.

It is very important that hospitals report C-Codes as well as the associated device costs. This will help inform and potentially increase future outpatient hospital payment rates.

CPT° Code	Code Description		
Inflatable	nflatable Penile Prosthesis- AMS 700™ and AMS Ambicor™ C-code C1813		
54405	Insertion of multi-component, inflatable penile prosthesis, including placement of pump, cylinders, and reservoir		
54406	Removal of all components of a multi-component, inflatable penile prosthesis without replacement of prosthesis		
54408	Repair of component(s) of a multi-component, inflatable penile prosthesis		
54410	Removal and replacement of all component(s) of a multi-component, inflatable penile prosthesis at the same operative session		
54411	Removal and replacement of all components of a multi-component inflatable penile prosthesis through an infected field at the same operative session, including irrigation and debridement of infected tissue		
Non-infla	table Penile Prosthesis- Spectra™ C-code C2622		
54400	Insertion of penile prosthesis; non-inflatable (semi-rigid)		
54415	Removal of non-inflatable (semi-rigid) or inflatable (self-contained) penile prosthesis, without replacement of prosthesis		
54416	Removal and replacement of non-inflatable (semi-rigid) or inflatable (self-contained) penile prosthesis at the same operative session		
54417	Removal and replacement of non-inflatable (semi-rigid) or inflatable (self-contained) penile prosthesis through an infected field at the same operative session, including irrigation and debridement of infected tissue		
Artificial	Urinary Sphincter- AMS 800™ C-code C1815		
53444	Insertion of tandem cuff (dual cuff)		
53445	Insertion of inflatable urethral/bladder neck sphincter, including placement of pump, reservoir, and cuff		
53446	Removal of inflatable urethral/bladder neck sphincter, including pump, reservoir, and cuff		
53447	Removal and replacement of inflatable urethral/bladder neck sphincter including pump, reservoir, and cuff at the same operative session		
53448	Removal and replacement of inflatable urethral/bladder neck sphincter including pump, reservoir, and cuff through an infected field at the same operative session including irrigation and debridement of infected tissue		
53449	Repair of inflatable urethral/bladder neck sphincter, including pump, reservoir, and cuff		
Male Sling	g- AdVance™ C-code C1771		
53440	Sling operation for correction of male urinary incontinence (eg, fascia or synthetic)		
53442	Removal or revision of sling for male urinary incontinence (eg, fascia or synthetic)		

# **Physician Payment - Medicare**

All rates shown are **2019 Medicare national averages**; actual rates will vary geographically and/or by individual facility. "Allowed Amount" is the amount Medicare determines to be the maximum allowance for any Medicare covered procedure. Actual payment will vary based on the maximum allowance less any applicable deductibles, co-insurances, etc.

CPT° Code	Short Descriptor	MD In-Office Medicare Allowed Amount	MD In-Facility Medicare Allowed Amount	Total Office-Based RVUs	Total Facility-Based RVUs
Inflatable	e Penile Prosthesis- AMS 700™ and AMS Ambicor™				
54405	Insertion of inflatable penile prosthesis	N/A	\$843	N/A	23.40
54406	Removal of inflatable penile prosthesis	N/A	\$762	N/A	21.13
54408	Repair of inflatable penile prosthesis	N/A	\$824	N/A	22.87
54410	Removal & replacement of inflatable penile prosthesis	N/A	\$897	N/A	24.89
54411	Removal & replacement of inflatable penile prosthesis through infected field	N/A	\$1,070	N/A	29.70
Non-infla	atable Penile Prosthesis- Spectra™				
54400	Insertion of non-inflatable penile prosthesis	N/A	\$553	N/A	15.34
54415	Removal of non-inflatable or inflatable penile prosthesis	N/A	\$551	N/A	15.30
54416	Removal & replacement of non-inflatable or inflatable penile prosthesis	N/A	\$742	N/A	20.58
54417	Removal & replacement of non-inflatable or inflatable penile prosthesis through infected field	N/A	\$936	N/A	25.97
Artificia	Urinary Sphincter- AMS 800™				
53444	Insertion of tandem cuff	N/A	\$826	N/A	22.93
53445	Insertion of inflatable urethral/bladder neck sphincter	N/A	\$785	N/A	21.78
53446	Removal of inflatable urethral/bladder neck sphincter	N/A	\$669	N/A	18.57
53447	Removal & replacement of urethral/bladder neck sphincter	N/A	\$842	N/A	23.37
53448	Removal & replacement of urethral/bladder neck sphincter through infected field	N/A	\$1,333	N/A	36.98
53449	Repair of inflatable urethral/bladder neck sphincter	N/A	\$638	N/A	17.69
Male Slir	Male Sling- AdVance™				
53440	Sling operation for male SUI	N/A	\$785	N/A	21.78
53442	Removal or revision of sling for male SUI	N/A	\$816	N/A	22.64

<sup>&</sup>quot;N/A" indicates that Medicare has not deemed this procedure to be reimbursable in this setting.

# **Hospital Outpatient and ASC Payment - Medicare**

CPT° Code	Short Descriptor	Hospital Outpatient Medicare Allowed Amount	ASC Medicare Allowed Amount	
Inflatable Penile Prosthesis- AMS 700™ and AMS Ambicor™ (C-code: C1813)				
54405	Insertion of inflatable penile prosthesis	\$16,320	\$13,839	
54406	Removal of inflatable penile prosthesis	\$2,927	\$1,368	
54408	Repair of inflatable penile prosthesis	\$4,021	\$1,912	
54410	Removal & replacement of inflatable penile prosthesis	\$16,320	\$13,629	
54411	Removal & replacement of inflatable penile prosthesis through infected field	\$16,320	N/A	
Non-inflatable Penile Prosthesis- Spectra™ (C-code: C2622)				
54400	Insertion of non-inflatable penile prosthesis	\$16,320	\$13,422	
54415	Removal of non-inflatable or inflatable penile prosthesis	\$2,927	\$1,368	
54416	Removal & replacement of non-inflatable or inflatable penile prosthesis	\$16,320	\$13,611	
54417	Removal & replacement of non-inflatable or inflatable penile prosthesis through infected field	\$16,320	N/A	
Artificial	Artificial Urinary Sphincter- AMS 800™ (C-code: C1815)			
53444	Insertion of tandem cuff	\$16,320	\$13,003	
53445	Insertion of inflatable urethral/bladder neck sphincter	\$16,320	\$13,782	
53446	Removal of inflatable urethral/bladder neck sphincter	\$4,021	\$1,912	
53447	Removal & replacement of urethral/bladder neck sphincter	\$16,320	\$13,522	
53448	Removal & replacement of urethral/bladder neck sphincter through infected field	N/A	N/A	
53449	Repair of inflatable urethral/bladder neck sphincter	\$4,021	\$1,912	
Male Sling- AdVance™ (C-code: C1771)				
53440	Sling operation for male SUI	\$7,651	\$6,159	
53442	Removal or revision of sling for male SUI	\$4,021	\$1,912	

<sup>&</sup>quot;N/A" indicates that Medicare has not deemed this procedure to be reimbursable in this setting.

## **Hospital Inpatient Payment - Medicare**

MS-DRG assignment is based on a combination of diagnoses and procedure codes reported. While MS-DRGs listed in this guide represent likely assignments, Boston Scientific cannot guarantee assignment to any one specific MS-DRG.

Possible MS-DRG Assignment	Description	Reimbursement
662	Minor bladder procedures with major complication or comorbidity (MCC)	\$19,419
663	Minor bladder procedures with complication or comorbidity (CC)	\$10,021
664	Minor bladder procedures without CC/MCC	\$7,244
673	Other kidney and urinary tract procedures with MCC	\$21,855
674	Other kidney and urinary tract procedures with CC	\$14,125
675	Other kidney and urinary tract procedures without CC/MCC	\$9,929
709	Penis procedures with CC/MCC	\$12,413
710	Penis procedures without CC/MCC	\$10,199

The patient's medical record must support the existence and treatment of the complication or comorbidity.

# **ICD-10 CM Diagnosis Codes**

ICD-10 CM Diagnosis Code	Description
Penile Prosthesis	
F52.21	Male erectile disorder
N52.01	Erectile dysfunction due to arterial insufficiency
N52.02	Corporo-venous occlusive erectile dysfunction
N52.03	Combined arterial insufficiency and corporo-venous occlusive erectile dysfunction
N52.2	Drug-induced erectile dysfunction
N52.31	Erectile dysfunction following radical prostatectomy
N52.32	Erectile dysfunction following radical cystectomy
N52.33	Erectile dysfunction following urethral surgery
N52.34	Erectile dysfunction following simple prostatectomy
N52.35	Erectile dysfunction following radiation therapy
N52.36	Erectile dysfunction following interstitial seed therapy
N52.37	Erectile dysfunction following prostate ablative therapy
N52.39	Other and unspecified postprocedural erectile dysfunction
N52.8	Other male erectile dysfunction
N52.9	Male erectile dysfunction, unspecified
Artificial Urinary Sphincter- AMS 800™	
N36.42	Intrinsic sphincter deficiency (ISD)
Male Sling- AdVance™	
N39.3	Stress incontinence
N39.42	Incontinence without sensory awareness
N39.45	Continuous leakage
N39.46	Mixed incontinence
N39.492	Postural (urinary) incontinence
N39.498	Other specified urinary incontinence
Penile Prosthesis, Artificial Urinary Sphincter-	AMS 800 <sup>™</sup> and Male Sling- AdVance <sup>™</sup>
T83.111A	Breakdown (mechanical) of implanted urinary sphincter, initial encounter
T83.121A	Displacement of implanted urinary sphincter, initial encounter
T83.191A	Other mechanical complication of implanted urinary sphincter, initial encounter
T83.410A	Breakdown (mechanical) of implanted penile prosthesis, initial encounter
T83.420A	Displacement of implanted penile prosthesis, initial encounter
T83.490A	Other mechanical complication of implanted penile prosthesis, initial encounter
T83.591A	Infection and inflammatory reaction due to implanted urinary sphincter, initial encounter
T83.598A	Infection and inflammatory reaction due to other prosthetic device, implant and graft in urinary system, initial encounter
T83.61XA	Infection and inflammatory reaction due to implanted penile prosthesis, initial encounter
T83.69XA	Infection and inflammatory reaction due to other prosthetic device, implant and graft in genital tract, initial encounter
T83.81XA	Embolism due to genitourinary prosthetic devices, implants and grafts, initial encounter
T83.82XA	Fibrosis due to genitourinary prosthetic devices, implants and grafts, initial encounter
T83.83XA	Hemorrhage due to genitourinary prosthetic devices, implants and grafts, initial encounter
T83.84XA	Pain due to genitourinary prosthetic devices, implants and grafts, initial encounter
T83.85XA	Stenosis due to genitourinary prosthetic devices, implants and grafts, initial encounter
T83.86XA	Thrombosis due to genitourinary prosthetic devices, implants and grafts, initial encounter

# ICD-10 CM Diagnosis Codes (cont'd)

ICD-10 CM Diagnosis Code	Description
Penile Prosthesis, Artificial Urinary Sphincter	r- AMS 800™ and Male Sling- AdVance™ (cont'd)
T83.89XA	Other specified complication of genitourinary prosthetic devices, implants and grafts, initial encounter
T83.9XXA	Unspecified complication of genitourinary prosthetic device, implant and graft, initial encounter
T85.79XA	Infection and inflammatory reaction due to other internal prosthetic devices, implants and grafts, initial encounter
T85.818A	Embolism due to other internal prosthetic devices, implants and grafts, initial encounter
T85.828A	Fibrosis due to other internal prosthetic devices, implants and grafts, initial encounter
T85.838A	Hemorrhage due to other internal prosthetic devices, implants and grafts, initial encounter
T85.848A	Pain due to other internal prosthetic devices, implants and grafts, initial encounter
T85.858A	Stenosis due to other internal prosthetic devices, implants and grafts, initial encounter
T85.868A	Thrombosis due to other internal prosthetic devices, implants and grafts, initial encounter
T85.898A	Other specified complication of other internal prosthetic devices, implants and grafts, initial encounter

# **ICD-10 PCS Procedure Codes**

ICD-10 PCS Procedure Code	Description
Penile Prosthesis	
OVUSOJZ	Supplement Penis with Synthetic Substitute, Open Approach
OVPSOJZ	Removal of Synthetic Substitute from Penis, Open Approach
OVWSOJZ	Revision of Synthetic Substitute in Penis, Open Approach
Artificial Urinary Sphincter- AMS 800™	
OTHCOLZ	Insertion of Artificial Sphincter into Bladder Neck, Open Approach
OTHDOLZ	Insertion of Artificial Sphincter into Urethra, Open Approach
OTPBOLZ	Removal of Artificial Sphincter from Bladder, Open Approach
OTPDOLZ	Removal of Artificial Sphincter from Urethra, Open Approach
OTWBOLZ	Revision of Artificial Sphincter in Bladder, Open Approach
OTWDOLZ	Revision of Artificial Sphincter in Urethra, Open Approach
Male Sling- AdVance™	
OTUCOJZ	Supplement Bladder Neck with Synthetic Substitute, Open Approach
OTUDOJZ	Supplement Urethra with Synthetic Substitute, Open Approach
OTPBOJZ	Removal of Synthetic Substitute from Bladder, Open Approach
OTPDOJZ	Removal of Synthetic Substitute from Urethra, Open Approach
OTWBOJZ	Revision of Synthetic Substitute in Bladder, Open Approach
OTWDOJZ	Revision of Synthetic Substitute in Urethra, Open Approach

Please note: this coding information may include codes for procedures for which Boston Scientific currently offers no cleared or approved products. In those instances, such codes have been included solely in the interest of providing users with comprehensive coding information and are not intended to promote the use of any Boston Scientific products for which they are not cleared or approved. The Health Care Provider (HCP) is solely responsible for selecting the site of service and treatment modalities appropriate for the patient based on medically appropriate needs of that patient and the independent medical judgement of the HCP.

Health economic and reimbursement information provided by Boston Scientific Corporation is gathered from third-party sources and is subject to change without notice as a result of complex and frequently changing laws, regulations, rules, and policies. This information is presented for illustrative purposes only and does not constitute reimbursement or legal advice. Boston Scientific encourages providers to submit accurate and appropriate claims for services. It is always the provider's responsibility to determine medical necessity, the proper site for delivery of any services, and to submit appropriate codes, charges, and modifiers for services rendered. It is also always the provider's responsibility to understand and comply with Medicare national coverage determinations (IxCD), and any other coverage requirements established by relevant payers which can be updated frequently. Boston Scientific recommends that you consult with your payers, reimbursement specialists, and/or legal counsel regarding coding, coverage, and reimbursement matters. Boston Scientific does not promote the use of its products outside their FDA-approved label. Information included herein is current as of November 2018 but is subject to change without notice. Rates for services are effective January 1, 2019.

Payer policies will vary and should be verified prior to treatment for limitations on diagnosis, coding, or site of service requirements. The coding options listed within this guide are commonly used codes and are not intended to be an all-inclusive list. We recommend consulting your relevant manuals for appropriate coding options.

Physician payment rates are 2019 Medicare national averages. Source: Centers for Medicare and Medicaid Services. CMS Physician Fee Schedule – November 2018 release, CMS-1693-F file. https://www.cms.gov/Medicare/Medicare-Fee-for-Service-Payment/PhysicianFeeSched/PFS-Federal-Regulation-Notices-Items/CMS-1693-F. html.

The 2019 National Average Medicare physician payment rates have been calculated using a 2019 conversion factor of \$36.0391. Rates subject to change

Hospital outpatient payment rates are 2019 Medicare OPPS Addendum B national averages. Source: Centers for Medicare and Medicaid Services. CMS OPPS – January 2019 release, CMS-1695-FC file. https://www.cms.gov/Medicare/Medicare-Fee-for-Service-Payment/HospitalOutpatientPPS/Hospital-Outpatient-Regulations-and-Notices-Items/CMS-1695-FC.html?DLPage=1&DLEntries=10&DLSort=2&DLSortDir=descending.

ASC payment rates are 2019 Medicare ASC Addendum AA national averages. ASC rates are from the 2018 Ambulatory Surgical Center Covered Procedures List. Source: Centers for Medicare and Medicaid Services. CMS ASC – January 2019 release, CMS-1695-FC file. https://www.cms.gov/Medicare/Medicare-Fee-for-Service-Payment/ASCPayment/ASC-Regulations-and-Notices-Items/CMS-1695-FC.html?DLPage=1&DLEntries=10&DLSortDir=descending.

National average (wage index greater than one and hospital submitted quality data and is a meaningful HER user) MS-DRG rates calculated using the national adjusted full update standardized labor, non-labor, and capital amounts (\$6,109.24). Source: August 2, 2018 Federal Register, CMS-1694-FR. FY 2019 rates.

ICD-10 MS-DRG definitions from the CMS ICD-10-CM/PCS MS-DRG v36.0 Definitions Manual. Source: https://www.cms.gov/ICD10Manual/version36-fullcode-cms/fullcode cms/P0001.html

#### Sequestration Disclaimer

Rates referenced in these guides do not reflect Sequestration, automatic reductions in federal spending that will result in a 2% across-the-board reduction to ALL Medicare rates as of January 1, 2019.

#### CPT® Disclaime

Current Procedural Terminology (CPT) Copyright 2018 American Medical Association. All rights reserved. CPT is a registered trademark of the American Medical Association. Applicable FARS/DFARS Restrictions apply to government use. Fee schedules, relative value units, conversion factors, and/or related components are not assigned by the AMA, are not part of CPT, and the AMA is not recommending their use. The AMA does not directly or indirectly practice medicine or dispense medical services. The AMA assumes no liability for data contained or not contained herein.

All trademarks are the property of their respective owners.



Advancing science for life™

Boston Scientific Corporation 300 Boston Scientific Way Marlborough, MA 01752-1234 www.bostonscientific.com/reimbursement

# Ordering Information 1.800.328.3881

©2019 Boston Scientific Corporation or its affiliates. All rights reserved.

Effective: 1JAN2019 Expires: 31DEC2019 MS-DRG Rates Expire: 30SEP2019 MH-445008-AC FFR 2019